ACROPOLIS RESTORATION SERVICE

THE RESTORATION OF THE **ACROPOLIS MONUMENTS** THE FOUR MONUMENTS ON THE SACRED ROCK OF THE **ATHENIAN ACROPOLIS, THE PARTHENON, THE PROPYLAIA,** THE ERECHTHEION AND THE **TEMPLE OF ATHENA NIKE**, WERE CONSTRUCTED ENTIRELY OF WHITE MARBLE. THEIR INGENIOUS DESIGN, THE **RICHNESS AND INTEGRITY OF**

THE FIGURES, AS WELL AS THE PERFECTION OF THE WORK **ITSELF, MEANT THAT THEY** WERE GREATLY ADMIRED **EVEN IN ANTIQUITY. BUILT IN** THE 5TH CENTURY B.C., DURING WHAT IS KNOWN AS THE **CLASSICAL PERIOD, THEY ARE TODAY NOT ONLY A FOCAL POINT OF GREEK HISTORY, BUT** THEY ARE ALSO A UNIVERSAL **POSSESSION OF WORLD** CULTURAL HERITAGE.

TO CONFRONT THE SEVERE PROBLEMS OF THE MONUMENTS, SUCH AS CRACKS IN THE MARBLE FROM THE OXIDATION OF THE **EXTENSIVE IRON REINFORCEMENTS OF THE** EARLIER RESTORATION **INTERVENTIONS, AS WELL AS** DAMAGE FROM OTHER **CAUSES, INCLUDING EXPLOSIONS, EARTHQUAKES,** BOMBARDMENTS AND THE EROSION OF THE SURFACES FROM

ENVIRONMENTAL FACTORS, IT WAS NECESSARY TO CARRY **OUT SERIOUS INTERVENTIONS.** THE MAIN CHARACTERISTICS **OF THESE INTERVENTIONS ARE** THE INTERDISCIPLINARY **APPROACH TO THE ENTIRE PROJECT, SYSTEMATIC** SCHOLARLY RESEARCH, **DETAILED DOCUMENTATION**, THE HIGH QUALITY OF THE WORK AND THE USE OF ADVANCED TECHNOLOGICAL **APPLICATIONS.**

THE INTERVENTIONS ARE **INSPIRED BY THE SPIRIT OF THE** "CHARTER OF VENICE" AND THEY ADHERE TO THE PRINCIPLES OF REVERSIBILITY AND RESPECT FOR THE **AUTHENTIC MATERIAL AND THE ANCIENT SYSTEM OF** CONSTRUCTION. THE SECTIONS OF THE MONUMENTS THAT SHOW SIGNS OF DAMAGE AND FRACTURE ARE DISMANTLED AND THE MEMBERS ARE CONSERVED ON THE GROUND. THE FRAGMENTS OF THE

ANCIENT ARCHITECTURAL MEMBERS ARE RE-JOINED USING TITANIUM RODS AND ARE THEN SET AGAIN IN THE POSITIONS THEY OCCUPIED IN **ANTIQUITY; ONLY IN SPECIAL CASES ARE THEY SET IN** SIMILAR POSITIONS. WHEREVER IT IS FOUND TO BE NECESSARY, THE MISSING PARTS OF THE MEMBERS ARE FILLED IN WITH **NEW PENTELIC MARBLE IN** ORDER TO RECOVER THEIR **AUTHENTIC FORM AND** STRUCTURAL INDEPENDENCE.

TO AVOID FURTHER DAMAGE, THE ARCHITECTURAL SCULPTURES ARE TRANSFERRED TO THE ACROPOLIS MUSEUM AND ARE REPLACED ON THE MONUMENTS THEMSELVES BY FAITHFUL COPIES IN ARTIFICIAL STONE.

PROPYLAIA

SYSTEMATIC RESEARCH ON THE PRESERVED ARCHITECTURAL MATERIAL AND INTERVENTIONS CARRIED

OUT ON THE CEILINGS OF THE EAST PORTICO AND WEST HALL OF THE MONUMENT, LED TO THE RESTORATION OF **EXTENSIVE SECTIONS OF THE** MARBLE CEILINGS OF THE **PROPYLAIA, WITH MINOR ADDITIONS OF NEW MARBLE, OVER AN AREA TWICE THAT OF** THE EARLIER RESTORATION. **MOREOVER, THE** SUPERSTRUCTURE OF THE SOUTH WING WAS RESTORED **BY USING ANCIENT MATERIAL** FOUND LYING NEAR THE

MONUMENT AND THE COLUMNS **OF THE WEST FAÇADE WERE** FILLED WITH NEW MATERIAL. **COMPLETION OF THE WORK**, **MOREOVER, HAS PROVIDED A** FULLER IDEA OF THE LUXURIOUS ROOFED SPACE OF **ONE OF THE MOST IMPRESSIVE** MONUMENTS OF CLASSICAL ANTIQUITY.

PARTHENON

THE PROJECT OF RESTORING THE PARTHENON, THE MOST IMPORTANT BUILDING ON THE **SACRED ROCK, DEDICATED TO ATHENA, PATRON GODDESS OF** THE CITY OF ATHENS, BEGAN IN THE DECADE OF THE 1980'S WITH THE EAST END OF THE MONUMENT. THE INTERVENTIONS CONCERNED THE CONSOLIDATION OF THE MEMBERS OF THE ENTABLATURE AND THE **REMOVAL AND REPLACEMENT OF ALL THE ORIGINAL METOPES** WITH CAST COPIES.

IN THE EAST PORCH OF THE MONUMENT THE INTERIOR SIX **COLUMN COLONNADE OF THE PRONAOS WAS RESTORED** WITH FILLINGS OF NEW MARBLE. IN THE **CORRESPONDING COLONNADE** OF THE OPISTHONAOS, CONSOLIDATION OF THE **ANCIENT COLUMNS THAT HAD** BEEN UNDISTURBED SINCE **ANTIQUITY WAS CARRIED OUT** IN SITU WITH SPECIAL **INJECTIONS. ON THE NORTH** SIDE, THE EIGHT COLUMNS IN

THE MIDDLE (FROM THE 4TH TO THE 11TH FROM THE EAST) AND THE CORRESPONDING PARTS OF THE OVERLYING MEMBERS WERE DISMANTLED, RESTORED AND RESET IN THEIR **AUTHENTIC POSITIONS. THE BLOCKS OF THE FRIEZE OF THE** WEST SIDE UNDERWENT **CONSERVATION AND CLEANING** WITH REMOVAL OF THE POLLUTANTS AND BLACK FILM THAT COVERED THEM, BY **MEANS OF AN ORIGINAL LASER APPLICATION. RESTORATION**

WORKS HAVE BEEN CONDUCTED ON THE PEDIMENT OF THE MONUMENT'S WEST SIDE, WHEREAS THE RESTORATION OF THE TEMPLE'S LONG WALLS IS IN PROGRESS.

ERECHTHEION

THE RESTORATION OF THE ERECHTHEION IS THE FIRST INTERVENTION THAT WAS CARRIED OUT ON THE ACROPOLIS, UNDER THE SCHOLARLY AUTHORITY OF THE COMMITTEE FOR **CONSERVATION OF THE ACROPOLIS MONUMENTS** (ESMA), DURING THE PERIOD 1979-1987. RESTORATION WAS **CONCENTRATED ON THE GREATER PART OF THE WALLS,** THE CEILINGS OF THE NORTH AND SOUTH PORCHES AND ON THE EAST FAÇADE OF THE MONUMENT. THE CARYATIDS, THE FAMOUS SCULPTURES THAT SUPPORTED THE ROOF **OF THE SOUTH PORCH, WERE** TAKEN TO THE ACROPOLIS

MUSEUM FOR THEIR PROTECTION; EXACT COPIES OF ARTIFICIAL STONE HAVE REPLACED THEM ON THE MONUMENT ITSELF.

ATHENA NIKE

THE SERIOUS DAMAGE AND STRUCTURAL PROBLEMS OF THE MONUMENT NECESSITATED COMPLETE DISMANTLING OF ALL ITS 333 MEMBERS. THE PROGRAMME INCLUDED RESETTING OF THE MEMBERS OF THE MARBLE TEMPLE IN THEIR AUTHENTIC POSITIONS AND THE CONSERVATION OF THE EARLIER POROS STONE SHRINE OF THE GODDESS, THAT **IS PRESERVED WITHIN THE CLASSICAL BASTION (PYRGOS), BENEATH THE MARBLE TEMPLE. THE FRIEZE BLOCKS** THAT WERE TAKEN FOR **PROTECTION TO THE ACROPOLIS MUSEUM, HAVE** BEEN REPLACED ON THE MONUMENT BY CAST COPIES.

A NEW PROGRAMME OF ANASTELOSIS AND **CONSERVATION OF THE** SURFACES OF THE MONUMENTS OF THE **ACROPOLIS WAS INAUGURATED** IN 2011. THE MOST SIGNIFICANT **INTERVENTIONS ARE BEING CARRIED OUT ON THE TWO CORNERS OF THE WEST SIDE OF THE PARTHENON, IN THE** SOUTH WING OF THE **PROPYLAIA AND ON THE SOUTH** WALL OF THE CENTRAL **BUILDING OF THE MONUMENT.**

THE WALLS AND THE ROCK **CONSOLIDATION WORKS ON** THE ROCKY INCLINES OF THE **ACROPOLIS WERE CONDUCTED DURING THE 1980'S AND 1990'S.** THE INSTALLATION OF SYSTEMS OF INSTRUMENTAL **OBSERVATION ON SELECTED AREAS OF THE WALLS, HELPED** TO COLLECT DATA ON THEIR **CHANGES AND DISTORTIONS, IN ADDITION, RESTORATION WORKS HAVE**

BEEN CARRIED OUT SINCE 2015. THE WORKS HAVE BEEN **COMPLETED IN THE AREA OF** THE SOUTH WALL BETWEEN THE 6TH AND 7TH BUTTRESS, ON THE SOUTHEAST CORNER AND **IN PARTS OF THE AREAS B17** AND B14 OF THE NORTH WALL. THE WORKS CONTINUE AND FOLLOW THE PRIORITIES SET BY THE STRATEGIC PLAN FOR THE RESTORATION OF THE **ACROPOLIS WALLS.**

THIS LEAFLET WAS TRANCRIBED AND PRINTED AT THE PRINTING DEPARTMENT OF THE LIGHTHOUSE FOR THE BLIND OF GREECE

ITS PRODUCTION IS A DONATION FROM THE ONASSIS FOUNDATION TO THE MINISTRY OF CULTURE AND SPORTS